Winstone Aggregates | Conditions of Entry

Yaldhurst Quarry & Cleanfill

» By entering Yaldhurst Quarry & Cleanfill, customers accept and agree to be bound by the following terms and conditions of entry:

1 General

- » Customers must adhere to the Yaldhurst Quarry & Cleanfill acceptance criteria as set out at part 2 of this document. By entering Yaldhurst Quarry & Cleanfill, customers are declaring and warranting that the material they carry meets this acceptance criteria.
- » Acceptance of any material at Yaldhurst Quarry & Cleanfill is at the discretion of Winstone Aggregates. Winstone Aggregates reserves the right to decline entry into Yaldhurst Quarry & Cleanfill by any loads not meeting the acceptance criteria set out in part 2 of this document. Furthermore, if a load that has entered Yaldhurst Quarry & Cleanfill is subsequently determined to be non-compliant with the acceptance criteria, it is to be removed from site immediately and suitably disposed of. As set out at part 3 of this document, customers will be responsible for removal and disposal of the material and will be responsible for all associated costs.
- » These conditions of entry are based on the Winstone Aggregates consent requirements and applicable Council bylaws. Customers entering Yaldhurst Quarry & Cleanfill agree to comply with all relevant Council bylaws.

2 Acceptance Criteria

» The Ministry for the Environment defines cleanfill as:

"Material that does not undergo any physical, chemical, or biological transformations that will cause adverse environmental effects or health effects once it is placed in a cleanfill. Cleanfill material has no potentially hazardous content and must not be contaminated by or mixed with any other non cleanfill material"

- » In general terms, materials that can be brought onto the Yaldhurst Quarry & Cleanfill site are limited to:
 - Uncontaminated soils, rocks, gravels, sand, silt and clay
 - Unlaminated glass containing no fluids
 - Bricks
 - Concrete
 - Ceramics
 - Weathered dry asphalt
 - Tiles
 - Road metal
 - Untreated wood comprising less than 1% of any load by volume
 - Vegetative material comprising less than 5% of any load by volume

- » Materials that CANNOT be brought onto the Yaldhurst Quarry & Cleanfill site include, but are not limited to:
 - Materials that may present a risk to human or animal health such as medical waste, radioactive waste, asbestos or hazardous materials
 - Cables, carpet, containers, electrical insulation, household waste, wet paint, wet or dry lead-based paint, plastics
 - Wet asphalt, contaminated soils, dredging spoil, laminated wood, treated wood, separated metals, tar and tyres
 - Hydro excavated waste / fill

2.1 Pre-Approval Criteria

- » Please be advised that the origin of fill can also affect its compliance with the Yaldhurst Quarry & Cleanfill acceptance criteria. Particular sites (e.g. horticultural, heavy industry, petrol stations) may have contaminated soil or fill due to the work that has, or currently is, carried out on these sites. Any material deposited at Yaldhurst Quarry & Cleanfill shall not be sourced from a site where activities associated with the Ministry for the Environment Hazardous Activities and Industries List (HAIL) have been, or are being, undertaken as per Environment Canterbury Listed Land Use Register (LLUR) unless the soil has been shown to contain compounds at or below maximum values of Background Concentrations of Selected Trace Elements in Canterbury Soils (T&T, 2006).
- » If the fill originates from one such site (HAIL), the material must be tested prior to being accepted at Yaldhurst Quarry & Cleanfill. The client must provide documentation of the suitability of the fill prepared by a Suitably Qualified and Experienced Practitioner (SQEP) in the form of a Site Investigation Report or Site Validation Report, that has been prepared in accordance with the Ministry for Environment Contaminated Land Guidelines No 1 and No 5, November 2003 (or equivalent standards as approved in writing by the Manager) with reference to any contaminants that could reasonably be expected to be present due to the current and former land use of the site of origin of the material. The report must include test results from a laboratory with IANZ accreditation.
- » It is the responsibility of the customer to get this testing undertaken.
- » We encourage customers to check the status of the site where the fill originates on Environment Canterbury LLUR website as early as possible prior to disposal and/or contact us to work through the specifics of any particular job. This helps avoid trucks being turned away at the weighbridge.
- » Environment Canterbury Listed Land Use Register (LLUR): https://llur.ecan.govt.nz/
- » Ministry for the Environment Hazardous Activities and Industries List (HAIL):

https://www.mfe.govt.nz/land/hazardous-activities-and-industries-list-hail

3 Non-complying material

- » Winstone Aggregates carries out inspections and random testing of material deposited at Yaldhurst Quarry & Cleanfill and on occasion discovers material which does not meet the acceptance criteria set out at part 2 of this document. Such material is quarantined, and Winstone Aggregates will give the customer responsible for the load(s) notice of that fact (via a Removal Notice). The customer must (at the customer's cost) remove the quarantined load(s), and potentially any other material originating from the same source that is deemed by Winstone Aggregates to be unsuitable to stay on site, and indemnify Winstone Aggregates for any costs it incurs as a result of such removal.
- » If a customer does not comply with the Removal Notice within 5 days of receipt, Winstone Aggregates reserves the right to remove the load(s) and any other material originating from the same source that is deemed by Winstone Aggregates to be unsuitable to stay on site, and dispose of the load(s) at a suitable facility. Customers must fully reimburse and indemnify Winstone Aggregates for any costs incurred as a result of such removal and subsequent disposal.

4 Being a good neighbour

- » Yaldhurst Quarry & Cleanfill is located on a busy road with several residential neighbours. Your assistance in helping Winstone Aggregates to be a good neighbour is appreciated. Please consider the following when planning to use the site:
 - The site opening hours: Monday to Friday 7.30am 4.30pm

Saturday / Sunday / Public Holidays - closed

- -Trucks are not to arrive before 7:30am, and at no time are they to queue or park outside the site.
- » Trucks are to arrive on site no later than 15 minutes before closing to allow time to tip and exit the site before closing.
- » No engine brakes are to be used when entering the site or around the site.

5 Health and Safety - Help us be Safe on Site

- » The Customer must ensure that all of the Customer's staff and contractors adhere to the following requirements:
- While on site you must always follow the instructions of site staff
- You must wear your PPE when out of your truck hard hat, steel toe boots, Hi-Viz vest, long sleeves, glasses and gloves
- Cell phones are not to be used while walking or driving on site
- On site the speed limit is 20km/h and your headlights and flashing beacons (if fitted) are to be turned on
- Stay in your cab when tipping. Once tipped check that your tailgate is secure
- No shunting on the tiphead
- Do not approach a working machine or other tipping vehicles until you have the operator's attention and the machine or vehicle has stopped
- Always follow the instructions of the spotter/operator while manoeuvring on site
- Do not get in between your tailgate and tray when cleaning out or get into your tray when raised
- Stay in your cab when you are being loaded. Once loaded, clean off your truck, re-distribute your load and check that your tailgate is secure
- Trucks will not be allowed to leave the site overloaded
- Prior to leaving site check between dual tyres and clear any rocks that are caught
- No person suspected of being under the influence of alcohol or drugs will be permitted on site

For any enquiries, please contact:

- » Yalhurst Quarry & Cleanfill Weighbridge on 03 342 8623
- » Canterbury Quarry Manager; Kristian Otto on 027 232 1237
- » Environmental Fill Specialist; Angela Klein on 027 504 3624

Yaldhurst Quarry & Cleanfill, 233 Old West Coast Road, RD 6, Yaldhurst, Christchurch