

---

## Compliance Inspection Report: 29 November 2022

---

<b><i>RM File No:</i></b>	RM150184
<b><i>Description of Activity:</i></b>	Extraction of gravel, removal of indigenous vegetation and associated earthworks
<b><i>Consent Holder:</i></b>	GBC Winstone Aggregates
<b><i>Inspection Dates:</i></b>	<u>Site inspection:</u> 10 November 2022

---

### **Compliance Summary**

1. Resource consent inspection has occurred since the last CLG meeting.

Two complaints received 10 November 2022, dust from Winstones and Peka Peka 2 Otaki sites, Site visit carried out water trucks were onsite and doing the circuit of the site. Due to high winds and the site being very dry water trucks were finding it hard to keep the whole site wet.

### **Points of Discussion**

- Two inspections occurred during the last six months.
- Acoustic Bund has lush grass, and will be mowed once the weather improves, no slumping has occurred during the last few weeks of heavy rain.
- Cypress hedge remains in good health, and we should see some good growth over the spring season.
- Winstones report will be tabled at the meeting.
- Work continues but extraction has slowed due to major projects nearing completion.
- Material stockpiles remain but no issues with stabilisation.
- Rehabilitation planting has had good growth, weeds will be sprayed in the next few of weeks when there is low wind.

**Signed**

**Simon Amos**  
**RMA Compliance Officer**

