

---

## Compliance Inspection Report: 30 May 2023

---

<b><i>RM File No:</i></b>	RM150184
<b><i>Description of Activity:</i></b>	Extraction of gravel, removal of indigenous vegetation and associated earthworks
<b><i>Consent Holder:</i></b>	GBC Winstone Aggregates
<b><i>Inspection Dates:</i></b>	<u>Site inspection:</u> 05 May 2023

---

### **Compliance Summary**

- One inspection occurred during the last six months.
- No service requests (complaints) were logged with Council since the last CLG meeting.
- Acoustic Bund in good shape and will be mowed once the weather improves.
- Cypress hedge well established, no damage during high winds over recent months.
- Work continues on stage 2, but extraction has slowed due to major projects nearing completion.
- Rehabilitation planting has been carried out around the edges of the newly battered edges of the ponds by Natural Habitat.

### **Points of Discussion from last meeting**

- Contact details for Greater Wellington Regional Council CLG representative (Emily McDowall) will be attending the meeting via Teams (remotely).
- Contacted Winstones re: Piezometer Report spoke to Gary who advised that they have heard nothing from GWRC regarding acceptance of report, he advised he will contact GWRC to see where it stands.
- Upon review of the Piezometer report as it is deemed to be confidential, I do not have the jurisdiction to release it to the public forum, that is something that Winstones will have to decide.

**New season planting**



**Cypress hedge and earth bund west of stage 1**



**Previous planting from last season.**



**Newly planted batter.**



**Simon Amos**  
**RMA Compliance Officer**

