



# Ashford Park Progress Report

## Briefing Paper Update

---

**Site:** Ashford Park

**Report Completed by:** Gary Edwards  
Kapiti Quarries and Crushing Manager  
Winstone Aggregates

**Date of Review:** 10<sup>th</sup> November 2023

**Strategic Objective:** Update to Community Liaison Group

**Briefing Paper for:** Update

---

# Contents

- 1.0    Actions from last CLG Meeting
- 2.0    Complaints
- 3.0    Water Quality Testing
- 4.0    Extraction
- 5.0    Planned work
- 6.0    Rehab and Maintenance

# Ashford Park Progress Report

## 1.0 Actions from last CLG Meeting

### 1.1

## 2.0 Complaints

### 2.1 Nil Complaints

## 3.0 Water Quality Testing

### 3.1 Appendix A attached

Link to site – <https://winstoneaggregates.co.nz/locations/otaki-quarry/ashford-park/>

## 4.0 Extraction

**Current Extraction** We are still extracting material in stage 2. This will continue well into next year before we move in to stage 3.

Over the period 10<sup>th</sup> May 2023 to 10<sup>th</sup> November 2023, 36,303m<sup>3</sup> of gravel was extracted from Ashford Park.

We have been crushing a lot of GAP material for several contractors for subdivisions and improvements to the roading network in the Region.

Ballast supply has increased due to the recent flooding in the Hawkes Bay Region.

Chip sealing season (Summer) has just started in the Horowhenua/Kapiti region.

## Current Stripping/Extraction area





## 5.0 Planned work

The new Noise bund between the OMRC and Ashford Park has been completed. Hydroseeding has also been completed and grass has started to take.





## . 6.0      **Rehab and Maintenance**

The Planting on the eastern side of Ashford Park that was completed in April 2023 is coming along nicely, Natural Habitats have a 4-year contract to look after and maintain these trees.



