
Compliance Inspection Report: 08 November 2023

<i>RM File No:</i>	RM150184
<i>Description of Activity:</i>	Extraction of gravel, removal of indigenous vegetation and associated earthworks
<i>Consent Holder:</i>	GBC Winstone Aggregates
<i>Inspection Dates:</i>	<u>Site inspection:</u> 08 November 2023

Compliance Summary

- One inspection occurred during the last six months.
- No service requests (complaints) were logged with Council since the last CLG meeting.
- Phone call direct from staff member driving passed entrance way that high winds were blowing up dust, I contacted Gary who had the water truck do a drive over to dampen down no further issues.
- Stage 1 acoustic Bund remains in good shape through last winter and due to be mowed.
- Cypress hedge well established, no damage during high winds over recent months.
- Works have picked up on stage 2 acoustic bund has been constructed and shaped will be planted next season.
- Planted areas showing good growth with very little loss of plants.

Looking to the west towards stage one planting.



Stage two acoustic bund constructed and shaped ready for planting.





Ongoing extraction from stage two.



**Simon Amos
RMA Compliance Officer**

